

**DIKES AND REVETMENT CONSTRUCTION/REPAIR
REPORT OF AS-BUILT CONDITIONS**

Contract Description: QJM FY14 MRM ³⁰⁰-195 Contract No.: W912P9-14-C-0411

Contractor - Prime: Patton-Tully Marine Sub: N/A

River Mile: 225.7 R Type of Structure (Constructed/Repaired): Chevron

Description of Work Performed: Raised & Repaired

Length of Structure Completed or Repaired Performance Shown by Stationing: 320'

Station: _____

Top Elevation: 424

Structure Coordinates: Start N 1113197

End N 1112892

E 493136

E 493054

Start Date: 9-Sep-14 End Date: 11-Sep-14

Tonnage Used at this Location: 2900 TN

General remarks or unique conditions: Raised & Repaired channel side Leg

Include sketch below or reference to attached sketch, as-built survey sheet, or marked up contract drawing where applicable:

**DIKES AND REVETMENT CONSTRUCTION/REPAIR
REPORT OF AS-BUILT CONDITIONS**

Contract Description: QJM FY14 MRM ³⁰⁰-195 Contract No.: W912P9-14-C-0411

Contractor - Prime: Patton Tully Marine Sub: N/A

River Mile: 225.5R Type of Structure (Constructed/Repaired): Chevron

Description of Work Performed: Raised & Repaired

Length of Structure Completed or Repaired Performance Shown by Stationing: 420'

Station: _____

Top Elevation: _____

Structure Coordinates: Start N 1114113

End N 1113716

E 493760

E 493756

Start Date: 9-Sep-14 End Date: 11-Sep-14

Tonnage Used at this Location: 2856 TN

General remarks or unique conditions: Raised & Repaired the Nose & Channel

Side Leg

Include sketch below or reference to attached sketch, as-built survey sheet, or marked up contract drawing where applicable: